



## Solder Terminations

Accelerometer connection



Pin1=-----  
 Pin2=Input  
 Pin3=GND (-UB)  
 Pin4=+UB

Sensor connection



Pin1=+24V  
 Pin2=---  
 Pin3=Input  
 Pin4=---  
 Pin5=GND

## Screw Terminations

sensor X 40



1 — + 24 V  
 2 — Input  
 3 — GND  
 4 —

Track control PNP-sensor X 4



1 — + 24 V, DC  
 2 —  
 3 — GND  
 4 — Input

